

## 3-Wire Potentiometer Input (Opt: 42) SI139

A reference voltage is supplied in terminal 8 of the SI139. The potentiometer or slide wire is connected between the reference (pin 8) and 0V (pin 9). The wiper output is then used as a voltage input to perform the re-transmit function

### Additional Specifications

Output reference voltage: 5V, 5mA  
Minimum potentiometer resistance: 1k

### Connection Diagram

