

Option 'A' Potentiometer Input SI236

Potentiometer Input:-

Potentiometer Input: 1kohm minimum

Auxiliary Voltage: 5Vdc.

